



The project: Peeling paint

The façade coating has come away and is peeling due to inadequate surface adhesion. This can be caused by a lack of primer or poor cleaning before the paint finish is applied. The paint finish is unable to dry uniformly due to dirt or a surface which absorbs the paint unevenly. Shrinkage cracks may appear and the paint may flake due to water penetrating.

The optimum KRAUTOL system solution:



Tiefgrund Plus
Acrylic hydrosol for
façade levelling primer
coats

FILLAN
Fibre-reinforced façade
non-woven paint liner

**ULTRA MAXX
Complete**
The 5-in-1 all-inclusive
solution for façades



KRAUTOL®

PROFESSIONAL

This is how it works: an optimum result in a few steps



Preparation and cleaning

Remove any loose or no longer firmly adhered paintwork with a steel brush or a scraper.

Clean the façade with a pressure washer and completely remove any dirt or stains.

Leave façade to dry out completely after cleaning, so the subsequent primer can penetrate the façade more effectively.



Primer

Prime the façade with **Tiefgrund Plus**. The high-quality primer strengthens the surface, ensuring uniform absorption.

This brings the advantage that the façade paint dries evenly and adheres securely while less paint is consumed.

Allow façade to dry thoroughly again after priming.



Prime and finish coat

Apply a primer coat of **Fillan** to level out any uneven surfaces in the structure. This smooths out the uneven surfaces by stripping the old coat of paint. Leave coat to dry out thoroughly.

Pre-treat the façade with **Ultra Maxx Complete** (diluted with a maximum of 10% water). The low viscosity of the paint ensures good penetration behaviour, thus achieving effective adhesion in the final coat.

Leave primer coat to dry out thoroughly. Then apply undiluted **Ultra Maxx Complete** façade paint.



Other façade projects

Simply scan the QR code with your smartphone or tablet and access additional information.

12/2017

Systematic façade protection